

IECEx CoC

Certified Service Facility

INTERNATIONAL ELECTROTECHNICAL COMMISSION **IEC Certification Scheme for Explosive Atmospheres**

for rules and details of the IECEx Scheme visit www.iecex.com

Certificate No.: IECEx UL S0005 Issue No: 2

Certificate history:

Status: Current Issue No. 2 (2019-02-14) Issue No. 1 (2018-05-03)

Date of Issue: 2019-02-14 Issue No. 0 (2017-04-28)

Derrick Corporation

Page 1 of 1

Derrick Corporation 590 Duke Road Buffalo, NY 14225

United States of America

Repair and Overhaul according to IEC 60079-19 Type of Service:

Flameproof Enclosure "d" Type of Protection:

Repair and overhaul of flameproof "d" motors Scope of Service:

Locations covered

Applicant:

Derrick Corporation 590 Duke Road Buffalo, NY by this Certificate:

United States of America

Facility Audit Report(s):

US/UL/FAR17.0001/02

This certificate is issued as verification that the Service Facility and associated locations were assessed and found to comply with the IECEx Scheme requirements, relating to the type and scope of service listed above. This certificate is granted subject to the conditions as set out in IECEx Scheme Rules, IECEx 03 and Operational Documents as amended.

Approved for issue on behalf of the IECEx

Katy A. Holdredge

Certification Body:

Senior Staff Engineer

Signature:

Date:

Position:

(for printed version)

2019-02-14

Kety a. Holbrige

- 1. This certificate and schedule may only be reproduced in full.
- 2. This certificate is not transferable and remains the property of the issuing body.
- 3. The Status and authenticity of this certificate may be verified by visiting the Official IECEx Website.

Certificate issued by:

UL LLC 333 Pfingsten Road Northbrook IL 60062-2096 **United States of America**

