



# IECEX CoC Certified Service Facility

## INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEX Scheme visit [www.iecex.com](http://www.iecex.com)

Certificate No.: **IECEX UL S0005** Page 1 of 1 Certificate history:  
Status: **Current** Issue No: 3 Issue 3 (2020-08-28)  
Date of Issue: 2020-08-28 Issue 2 (2019-02-14)  
Applicant: **Derrick Corporation** Issue 1 (2018-05-03)  
Derrick Corporation Issue 0 (2017-04-28)  
590 Duke Road  
Buffalo, NY 14225  
**United States of America**  
Type of Service: **Repair and Overhaul according to IEC 60079-19**  
Type of Protection: **Flameproof Enclosure "d"**  
Scope of Service: Repair and overhaul of flameproof "d" motors

Locations covered by this Certificate:

**Derrick Corporation**  
590 Duke Road  
Buffalo, NY 14225  
**United States of America**

Facility Audit Report:

[US/UL/FAR17.0001/00](#)  
[US/UL/FAR17.0001/03](#)

[US/UL/FAR17.0001/01](#)

[US/UL/FAR17.0001/02](#)

This certificate is issued as verification that the Service Facility and associated locations were assessed and found to comply with the IECEX Scheme requirements, relating to the type and scope of service listed above. This certificate is granted subject to the conditions as set out in IECEX Scheme Rules, IECEX 03 and Operational Documents as amended.

Approved for issue on behalf of the IECEX  
Certification Body:

**Katy A. Holdredge**

Position:

**Senior Staff Engineer**

Signature:  
(for printed version)

Date:

2020-08-28

1. This certificate and schedule may only be reproduced in full.
2. This certificate is not transferable and remains the property of the issuing body.
3. The Status and authenticity of this certificate may be verified by visiting [www.iecex.com](http://www.iecex.com) or use of this QR Code.



Certificate issued by:

**UL LLC**  
**333 Pfingsten Road**  
**Northbrook IL 60062-2096**  
**United States of America**

